Double Articulated Headrest Assembly



MA578500i

Used on units with Serial Number LM1035 thru LM1295, LN11051 thru LN1386, LP1002 thru LP1017, and LR1002 thru LR1010

Item	Part No.	Description	Qty.
	9A310xxx	Headlock Assembly w/upholstery (Includes Items 1 thru 18) {Specify Color - refer to "Upholstery Kit"}	
1	•	• Upholstered Headrest (Refer to Upholstery Kit")	Ref.
2	•	• Knob (Refer to "Upholstery Kit")	Ref.
3	• 029-2279-00	• Headlock Assembly (Includes Items 4 thru 18)	1
4	• • 040-0250-21	• • Set Screw	2
5	• • 020-0191-02	• • Housing	1
6	• • 057-0507-00	• •Pin Stop Block	2
7	• • 057-0509-00	• • Pivot Pin	2
8	• • 051-0877-00	• • Pin Housing	1
9	• • 051-0879-00	• • Release Button	1
10	• • 040-0006-92	• • Double Articulating Headrest Pivot	2
11	• • 030-1253-00	• • Tang Weldment	1
12	• • 016-0138-19	• • Spacer	2
13	• • 050-4291-00	• • Release Plate	1
14	• • 057-0508-00	• • Stop Pin	8
15	• • 025-0059-00	• • Spring	8
16	• • 040-0006-93	• • Screw	2
17	• • 051-0878-00	• • Spring Housing	1
18	• • 053-0050-12	• • Hole plug	1

Always Specify Model & Serial Number

© Midmark Corporation 2001 SF-1571 Rev. (3/02)

Printed in U.S.A.